Updated 25.2.2021

AVO series™



Service Catalogue

AVO *Harmony*® 135-87

ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com

AVO Harmony® 135-87

Exploded View



ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com

AVO Harmony® 135-87

Spare Part List*

No	Part no	Item	Pcs/product
1a	250-0034	Side glass element, left	1
1b	250-0033	Side glass element, right	1
2	434-0035	Shelf plate upper	1
2a	431-0011	Upper shelf holder	2
2b	434-0038	Shelf middle support	1
3	434-0034	Shelf plate lower	1
3a	431-0010	Lower shelf holder	2
3b	434-0038	Shelf middle support	1
4	V20-0004	Bottom plate include curtain	1
5	610-0018	Night curtain, L=772mm	1
6	200-0090	Mounting ferrule for side glass	12
7	200-0090	Mounting ferrule for front grill	2
8	V20-0003	Front grill include insulation	1
9	434-0006	Front grill support	1
10	434-0033	ECO frame upper list	1
11	200-0150	ECO frame	1
12	434-0055	ECO frame lower list	1
	120-0027	Led lightning	3

*The minimum period during which spare parts, necessary for the repair of the appliance is 8 years after placing the last unit of the model on the market.

ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com

AVO Harmony® 135-87

Cassette Exploded View



ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com

AVO Harmony® 135-87

Cassette Spare Part List*

No	Code	Item	Pcs / product
1	210-0193	EPP body top cover	1
2	210-0192	EPP body	1
3	102-0015	Evaporator	1
4	107-0006	Condenser fan motor	1
5	110-0003	Connection plug	1
6	101-0026	Compressor NLE11MN R290/230V	1
6.1	101-0026-1	Starting relay	1
7	200-0119	Re-vaporation tray	1
8	710-0002	Wheel rotating LPA-TPA50G	4
9	430-0032	the terminal strip	1
10	120-0017	Led-power SLT15-12VF	1
11	103-0012	Condenser	1
12	107-0001	Evaporator fan	2
13	434-0030	Evaporator fan fixing plate	1

*The minimum period during which spare parts, necessary for the repair of the appliance is 8 years after placing the last unit of the model on the market.

ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com

AVO Harmony® 135-87

Wiring Diagram



ASTE FINLAND OY
KOSKIVUORENKATU 5
30420 FORSSA | FINLAND

+358 (0)2 970 200 160
sales@astecoolers.com
www.astecoolers.com